
Palos Verdes Shelf Remediation Update


September 30, 2010





Record of Decision signed 9/30/09

- Maintain ICs program
- Cap area around outfalls
- Monitor natural recovery
- Assess at 2nd Five-Year Review
 whether
 additional actions
 warranted




Monitored Natural Recovery

- Reduction of DDTs
 & PCBs in sediment
- Reductive
 Dechlorination of DDE
- Modelling of sediment transport



Proposed Cap Area

 Capping: sealing sediment with a thick layer of silt and sand





Baseline Monitoring

- Sediment sampling
- Water column sampling
- Fish tracking study
- Seafood consumption survey

Sediment Sampling Locations Portuguese Bend Abalore Ors. Pr. Vicente Vongot. Royalda Pt. Fermin **Baseline Survey** Outfall Area Survey miles

Water Sampling Locations





Schedule

2011 Remedial design and studies

2012 Capping

2013 Post-cap monitoring, assessment of effectiveness